































## Вычисление числа степеней свободы механической системы

Определить число степеней свободы системы по формуле  $W = 3D - 2Ш - С$ .







Ответы

1	4
2	4
3	5
4	1
5	4
6	-1
7	0
8	1
9	0
10	4
11	2
12	3
13	-1
14	3
15	2
16	0
17	0
18	2
19	0
20	2
21	2
22	4
23	2
24	2
25	-1
26	4
27	2
28	4
29	0
30	4